







CURRENT	VOLTS	PHASE	CYCLE	R. P. M.	DIMENSIONS IN INCHES					
					A			B		
					1/4	1/2	3/4	1	1 1/2	2
ALTERNATING	220, 440, 550, OR 220-440	2	60	1725	15 15/16	17 3/16		9 7/16	10 13/16	
	110, 220, OR 110-220	1	60	1725	16 7/8			10 3/8		
	110, 220, OR 110-220	1	50	1425	17 5/16			10 13/16		
	220, 440, 550, OR 220-440	2	60	3450		17 7/8	18 11/16		11 3/8	12 3/16
	110, 220, OR 110-220	1	60	3450		18 1/16			12 3/16	
	110, 220, OR 110-220	1	50	2850						
	220, 440, 550, OR 220-440	2	60	1725						
	110, 220, OR 110-220	1	60	1725						
	220, 440, 550, OR 220-440	2	60	3450						
	110, 220, OR 110-220	1	60	3450						
	220, 440, 550, OR 220-440	2	60	1725						
	110, 220, OR 110-220	1	60	1725						

Gusher.

MOTOR DRIVEN
 MACHINE TOOL COOLANT PUMP

MODEL NO. 9050

WHEN ORDERING SPECIFY

MODEL NO. 9050
 MOTOR HORSE POWER, R.P.M. &
 CURRENT CHARACTERISTICS

1/2" N.P.T. DISCHARGE IS STANDARD;
 SPECIFY 1/4" IF PREFERRED

© 1956

THE RUTHMAN MACHINERY CO.
 CINCINNATI 2, OHIO.

DRAWING NO.
9050